

**CALIFORNIA REGIONAL WATER QUALITY CONTROL BOARD  
LOS ANGELES REGION**

101 CENTRE PLAZA DRIVE  
MONTEREY PARK, CA 91754-2156  
(213) 266-7500  
FAX: (213) 266-7600

SFUND RECORDS CTR  
2166-98952



SFUND RECORDS CTR  
**88148079**

August 2, 1995

MICHELSON FOOD SERVICES  
9324 San Fernando Road  
Sun Valley, CA 91352


**WELL INVESTIGATION PROGRAM - SITE INSPECTION (FILE NO. 111.2651)**

On July 25, 1995, your facility was inspected by staff of this Regional Board. The inspection focused mainly on past and present methods for handling chemicals and wastes at your facility.

Based on our observations and information presented to us, your facility has limited chemical usage (lacquer thinners and paint); therefore, no further action on your part is required at this time with respect to the Well Investigation Program. You are requested to notify this Board of any change in your operations including storage and handling of chemicals or processing and disposal of waste.

Please note that this letter in no way releases you from any chemical and/or waste handling requirements of this or any other agency.

Please contact Mr. Yue Rong at (213) 266-7604 if you have any questions.

  
HUBERT H. KANG  
Senior Water Resource  
Control Engineer

cc: ~~Mr.~~ David Seter, U.S. EPA Region IX